



Harvard Physics
Part 5 of 8

Large Vise Project
make from steel

"Screw Support"



Tolerance Chart
 .X = +/- .03
 .XX = +/- .01
 .XXX = +/- .005
 .XXXX = +/- .0005
 unless otherwise noted

drawn by S. Cotreau
03/05/2004