


Milling Machine Stop for "KURT" Vise
Part 1 of 3

Tolerance Chart
.XX = +/- .01
.XXX = +/- .005



Make from .88" square steel stock

33/64" drill through, 2 places as shown. (deburr holes after drilling)

one piece required
Drawn by S.P.C.
Sept. 28, 2004