



Harvard Physics  
2 pcs. required

Large Vise Project  
"jaw support rods"

make from brass  
part 2 of 8



Tolerance Chart  
 .X = +/- .03  
 .XX = +/- .01  
 .XXX = +/- .005  
 .XXXX = +/- .0005  
 unless otherwise noted

NOTE: part will be pinned in place at assembly  
 Drawn by S. Cotreau 03/08/2004